

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.		2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Company, C1-Q8C(11-11) Attn: Rob Tuell 3855 Lakewood Blvd. Long Beach, CA 90846		CAD08651000562845		A. State Manifest Document Number 95462845			
4. Generator's Phone (310) 496-6287 or (310) 593-3101				B. State Generator's ID HAHQ33005698			
5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc.		6. US EPA ID Number CAD000083121		C. State Transporter's ID 448018			
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (310) 510-4700			
9. Designated Facility Name and Site Address North Environmental Services 6215 South Boyle Avenue Los Angeles, CA 90058		10. US EPA ID Number CAD097030993		E. State Facility's ID 097030993		H. Facility's Phone (213) 588-7111	
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol	
a. RC Waste nitrating acid mixtures spent, 8, UN1826, PG II (D002)		002 DF		00570		P	
b. Rinse water with soap Non-RCRA hazardous waste liquid		002 DF		00775		P	
c.						I. Waste Number State 792 EPA/Other D002	
d.						State 133 EPA/Other NR	
J. Additional Descriptions for Materials Listed Above 11a. E0108200133AK Nitric acid from steam-heated Nitric acid Drums 11b. E0108200133AK Rinse water with soap		K. Handling Codes for Wastes Listed Above a. 01 b. 01 c. d.					
15. Special Handling Instructions and Additional Information 24 Hour emergency telephone number (800) 424-9300 (Chemtrec). DOT ERG# 11a)60 b)31 Site address: 19503 South Normandie Avenue, Torrance, CA 90502.							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month 06		Day 16	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Wilbur L. Fike		Signature Wilbur L. Fike		Month 06		Day 16	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month		Day	
19. Discrepancy Indication Space Item 11b! waste does not contain organics should be State Code 135 per Fred Winland then 11a) either toxic or irritant EPA-D001 D008 6-16-95 (310)							
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Jin-mo CHIU		Signature Jin-mo Chiu		Month 06		Day 16	

DO NOT WRITE BELOW THIS LINE.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Company, C1-Q8C (11-11) Attn: Rob Tuell 3855 Lakewood Blvd. Long Beach, CA 90846		1. Generator's US EPA ID No. CA D 0 8 9 5 1 0 0 0 5 6 2 8 4 5		A. State Manifest Document Number 95462845		
4. Generator's Phone (310) 496-6287 or (310) 593-3101		6. US EPA ID Number		B. State Generator's ID HA HQ 36005698		
5. Transporter 1 Company Name Laidlaw Environmental Services of CA, Inc.		6. US EPA ID Number CA D 0 0 0 0 8 3 1 2 1		C. State Transporter's ID 448018		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (310) 518-4700		
9. Designated Facility Name and Site Address Norris Environmental Services 5215 South Boyle Avenue Los Angeles, CA 90058		10. US EPA ID Number CA D 0 9 7 0 3 0 9 9 3		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone (213) 588-7111		
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
a. RQ, Waste nitrating acid mixtures spent, 8, UN1826, PG II (D002)		002	DF	00570	P	State 792 EPA/Other D002
b. Rinse water with soap Non-RCRA hazardous waste liquid		002	DF	00775	P	State 133 EPA/Other N/A
c.						State EPA/Other
d.						State EPA/Other
J. Additional Descriptions for Materials Listed Above 11a. E0108200006AC. Nitric acid from steam-heat Nitric acid Drums 11b. E0108200133AK. Rinse water with soap		K. Handling Codes for Wastes Listed Above a. b. c. d.				
15. Special Handling Instructions and Additional Information 24 Hour emergency telephone number (800) 424-9300 (Chemtree). DOT ERG# 11a)60 b)31 Site address: 19503 South Normandie Avenue, Torrance, CA 90502.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Robert G. Tuell, Jr.		Signature Robert G. Tuell, Jr.		Month Day Year 06/16/95		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Willbur L. Fife		Signature Willbur L. Fife		Month Day Year 06/16/95		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name						
		Signature		Month Day Year		

DO NOT WRITE BELOW THIS LINE.

NORRIS ENVIRONMENTAL SERVICES

LAND DISPOSAL RESTRICTION NOTIFICATION

Pursuant to CCR Title 22, section 66268.7 (40 CFR 268.7 (a)), I hereby notify that this waste shipment contains one or more of the following wastes restricted under the land disposal restrictions for which applicable treatment standards are set forth in CCR Title 22, section 66268.40 (40 CFR 268.40)

MANIFEST NUMBER <u>62845/95462845</u>		GENERATOR NAME <u>Douglas Aircraft Co</u>		EPA # <u>CAD086510005</u>	
RCRA HAZARDOUS WASTE INFORMATION					
N.E.S. PROFILE NUMBER/ MANIFEST LINE ITEM NUMBER	LIST ALL D, F, K, U & P CODES	SUBCATEGORY (IF ANY)	WASTEWATER*/ NONWASTEWATER		HAZARDOUS DEBRIS SUBJECT TO CCR Title 22, Sec. 66268.45
<u>E0106200006AC/a</u>	<u>D002</u>		<input type="checkbox"/> WW	<input checked="" type="checkbox"/> NWW	<input type="checkbox"/> For: <u>PH < 2.0</u>
<u>E0106200133AK/b</u>	<u>N/R</u>		<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____
			<input type="checkbox"/> WW	<input type="checkbox"/> NWW	<input type="checkbox"/> For: _____

ADDITIONAL INFORMATION FOR D001, D002, D012-43, F001-005 & F039 WASTE STREAMS: (check one)

☒ There are no underlying hazardous constituents (UHCs) present

☐ There are underlying hazardous constituents (UHCs) present which do not meet treatment standards per CCR Title 22, Section 66268.48
(Use the attached UTS Table and check the appropriate constituent (s) present in the waste stream)

DETERMINATION BASED UPON: (check one)

☒ Knowledge of the process generating the waste and the raw materials used and the reaction products

☐ Results from analytical testing Analytical results attached ☐ YES ☐ NO

TERM DEFINITIONS

* WASTEWATER - per CCR Title 22, section 66260.10, WASTE THAT CONTAINS LESS THAN 1% BY WEIGHT TOTAL ORGANIC CARBON (TOCs) AND/OR 1% BY WEIGHT TOTAL SUSPENDED SOLIDS (TSS).

** CALIFORNIA LIST - THE FOLLOWING HAZARDOUS WASTES ARE PROHIBITED FROM LAND DISPOSAL: per CCR Title 22, Section 66268.32

1. Liquid hazardous waste with a pH less than or equal to 2.0
2. Liquid hazardous waste containing PCB's at concentration of greater than or equal to 50 ppm
3. Liquid hazardous waste, including free liquids associated with any solids/sludge, containing free cyanide at concentrations greater than or equal to 1,000 mg/L
4. Liquid hazardous waste, including free liquids associated with any solids/sludge, containing metals at concentrations greater than or equal to the following:

ARSENIC	500 mg/L	MERCURY	20 mg/L
CADMIUM	100 mg/L	NICKEL	134 mg/L
CHROMIUM (VI)	500 mg/L	SELENIUM	100 mg/L
LEAD	500 mg/L	THALLIUM	130 mg/L
5. Liquid hazardous waste, that contains HOC's in total concentration greater than or equal to 1,000 mg/L
6. Non-liquid RCRA hazardous waste containing HOC's in total concentration greater than or equal to 1,000 mg/L

CERTIFICATION

I certify under penalty of law that I personally have examined and am familiar with the waste through analysis and testing, or through knowledge of the process generating the waste, to support this certification. I believe that the information that I submitted is true, accurate and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

Robert G. Tuell, Jr. Douglas Aircraft Co. Senior Plant Engineer

AUTHORIZED SIGNATURE COMPANY NAME TITLE

Robert G. Tuell, Jr. Robert G. Tuell, Jr. 06-16-95

AUTHORIZED SIGNATURE PRINTED NAME DATE

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest Document No.

2. Page 1

Information in the sh
is not required by Fe

C A D 0 8 6 5 1 0 0 0 5 6 2 8 4 5

of 1

3. Generator's Name and Mailing Address

Douglas Aircraft Company, C1-Q6C (11-11) Attn: Rob Tuell
3855 Lakewood Blvd. Long Beach, CA 90846

4. Generator's Phone ((310) 496- 6287 or (310) 593- 3101

A. State Manifest Document Number

95462845

B. State Generator's ID

H A H Q 3 6 0 0 5 6 9 8

C. State Transporter's ID

D. Transporter's Phone

(310) 518- 4700

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone

(213) 588-7111

5. Transporter 1 Company Name

6. US EPA ID Number

Laidlaw Environmental Services of CA, Inc. C A D 0 0 0 0 8 3 1 2 1

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

Norris Environmental Services
5215 South Boyle Avenue
Los Angeles, CA 90058

10. US EPA ID Number

C A D 0 9 7 0 3 0 9 9 3

11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

No.

Type

13. Total

Quantity

14. Unit

Wt/Vol

I. Waste Number

RQ, Waste nitrating acid mixtures spent, 8, UN1826,
PG II (D002)

0 0 2

DF

0 0 5 7 0

P

State 792

EPA/Other D002

Rinse water with soap
Non-RCRA hazardous waste liquid

0 0 2

DF

0 0 7 7 5

P

State 133

EPA/Other N/R

J. Additional Descriptions for Materials Listed Above

11a. E0106200006AC. Nitric acid from desmut term. Nitric acid Drums

11b. E0106200133AK. Rinse water with soap

K. Handling Codes for Wastes Listed Above

a.

b.

c.

d.

15. Special Handling Instructions and Additional Information

24 Hour emergency telephone number (800) 424- 9300 (Chemtrec). DOT ERG# 11a)60 b)31
Site address: 19503 South Normandie Avenue, Torrance, CA 90502.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

Robert G. Tuell, Jr.

Signature

Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month Day Year

DO NOT WRITE BELOW THIS LINE.